


序号	报告编号	发布日期	结论	影像资料
6	GX-B1598/24-5-24020	2024. 12. 6	实测钢丝绳有效截面积损失百分比最大为0.96%，小于5%为正常。	
7	GX-B1598/24-5-24021	2024. 12. 6	实测钢丝绳有效截面积损失百分比最大为2.32%，小于5%为正常。	

8	GX-B1598/24-5-24022	2024. 12. 6	实测钢丝绳有效截面积损失百分比最大为2.17%，小于5%为正常。	 2024/12/4
9	GX-B1598/24-5-24023	2024. 12. 6	实测钢丝绳有效截面积损失百分比最大为2.17%，小于5%为正常。	 2024/12/4
10	GX-B1310/21-5-24397	2024. 12. 16	符合标准要求。	 2024/11/28

11	GX-B1310/21-5-24398	2024. 12. 16	符合标准要求。		 A photograph showing a person wearing a dark jacket and a helmet, possibly a night vision or thermal imaging device, in a dark environment. The person is holding a device that is emitting a red light. The date '2024/11/28' is visible in the bottom right corner of the image.	
----	---------------------	--------------	---------	--	--	--