

序号	报告编号	发布日期	结论	影像资料
3	GX-B1451/20-1-24510~24519	2025. 1. 9	本次共检继电保护装置10台，9台继电保护装置所检项目合格	
4	GX-B1451/20-1-24520~24529	2025. 1. 9	本次共检继电保护装置10台，10台继电保护装置所检项目合格	

5	GX-B1451/20-1-24530~24537	2025. 1. 9	本次共检继电保护装置8台，8台继电保护装置所检项目合格	
6	GX-B1451/20-1-24538~24545	2025. 1. 9	本次共检继电保护装置8台，8台继电保护装置所检项目合格	

7	GX-B1451/20-1-24546~24547	2025. 1. 9	本次共检继电保护装置2台，2台继电保护装置所检项目合格	
8	GX-B1451/20-1-24548~24549	2025. 1. 9	本次共检继电保护装置2台，2台继电保护装置所检项目合格	

9	GX-B1451/20-1-24550	2025. 1. 9	所检项目合格	
10	GX-B1451/20-1-24551~24560	2025. 1. 9	本次共检继电保护装置10台，10台继电保护装置所检项目合格	

11	GX-B1310/21-1-24291	2025. 1. 9	符合标准要求	 A worker wearing a blue jacket, a red helmet, and safety glasses is working on a large, red industrial machine. The machine has a circular opening, and the worker is positioned inside or near it, possibly performing maintenance or inspection. A yellow timestamp '2024/12/18' is visible in the bottom right corner of the image.
12	GX-B1310/21-1-24292	2025. 1. 9	符合标准要求	 A worker wearing a blue jacket, a red helmet, and safety glasses is working on a large industrial machine. The machine is enclosed in a metal cage or safety enclosure. The worker is positioned inside the cage, possibly performing maintenance or inspection. A yellow timestamp '2024/12/18' is visible in the bottom right corner of the image.

13	GX-B1310/21-1-24293	2025. 1. 9	符合标准要求	
14	GX-B1428/21-1-24294	2025. 1. 9	无缺陷迹痕显示	

15	GX-B1310/21-1-24295	2025. 1. 9	符合标准要求	
16	GX-B1428/21-1-24296	2025. 1. 9	无缺陷迹痕显示	

17	GX-B1534/20-1-24103	2025. 1. 9	所检项目合格	 <p>2024.12.31</p>
18	GX-B1534/20-1-24104	2025. 1. 9	所检项目合格	 <p>2024.12.31</p>

19	GX-B1534/20-1-24105	2025. 1. 9	所检项目合格	
20	GX-B1302/23-1-24003	2025. 1. 9	综合判定：合格	

21	GX-B1451/20-1-24562~24577	2025. 1. 13	本次共检继电保护装置16台，16台继电保护装置所检项目合格	
22	GX-B1451/20-1-24578~24590	2025. 1. 13	本次共检继电保护装置13台，13台继电保护装置所检项目合格	

23	GX-B1451/20-1-24591~24603	2025. 1. 13	本次共检继电保护装置13台，13台继电保护装置所检项目合格	
24	GX-B1451/20-1-24604~24605	2025. 1. 13	本次共检继电保护装置2台，2台继电保护装置所检项目合格	

25	GX-B1451/20-1-24606~24626	2025. 1. 13	本次共检继电保护装置21台，21台继电保护装置所检项目合格	
26	GX-B1451/20-1-24627~24636	2025. 1. 13	本次共检继电保护装置10台，10台继电保护装置所检项目合格	

27	GX-B1451/20-1-24637~24647	2025. 1. 13	本次共检继电保护装置11台，11台继电保护装置所检项目合格	
28	GX-B1451/20-1-24648~24649	2025. 1. 13	本次共检继电保护装置2台，2台继电保护装置所检项目合格	

29	GX-B1310/21-1-24287	2025. 1. 13	符合标准要求	
30	GX-B1428/21-1-24288	2025. 1. 13	无缺陷迹痕显示	

31	GX-B1428/21-1-24289	2025. 1. 13	无缺陷迹痕显示	
32	GX-B1309/21-1-24032	2025. 1. 13	所检项目合格	

33	GX-B1500/21-1-24130	2025. 1. 13	综合判定：合格	 <p>2024.12.26</p>
34	GX-B1500/21-1-24131	2025. 1. 13	综合判定：合格	 <p>2024.12.26</p>

35	GX-B1500/21-1-24132	2025. 1. 13	综合判定：合格	
36	GX-B1539/22-1-24015	2025. 1. 13	所检项目合格	

37	GX-B1451/20-1-25001~25026	2025. 1. 14	本次共检高压开关柜 26台，26台高压开关柜所 检项目合格	
38	GX-B1451/20-1-25027~25035	2025. 1. 14	开关柜9台，9台高压开关柜	

39	GX-B1451/20-1-25036~25056	2025. 1. 14	本次共检高压开关设备21台，21台高压开关设备所检项目合格	
40	GX-B1324/21-1-25001~25009	2025. 1. 14	本次共检三相交流电动机9台，9台三相交流电动机所检项目合格	

41	GX-B1598/24-1-24069	2025. 1. 15	实测钢丝绳有效截面积损失百分比最大为1.73%， 小于5%为正常	
42	GX-B1598/24-1-24070	2025. 1. 15	测钢丝绳有效截面积损失百分比最大为1.79%，小 于5%为正常	

43	GX-B1598/24-1-24071	2025. 1. 15	实测钢丝绳有效截面积损失百分比最大为1.65%， 小于5%为正常	
44	GX-B1598/24-1-24072	2025. 1. 15	实测钢丝绳有效截面积损失百分比最大为1.54%， 小于5%为正常	

45	GX-B1598/24-1-24073	2025. 1. 15	实测钢丝绳有效截面积损失百分比最大为0.78%， 小于5%为正常	
46	GX-B1598/24-1-24074	2025. 1. 15	实测钢丝绳有效截面积损失百分比最大为1.05%， 小于5%为正常	

47	GX-B1598/24-1-24075	2025. 1. 15	实测钢丝绳有效截面积损失百分比最大为1.86%， 小于5%为正常	 <p>2024/12/30</p>
48	GX-B1598/24-1-24076	2025. 1. 15	实测钢丝绳有效截面积损失百分比最大为1.17%， 小于5%为正常	 <p>2024/12/30</p>


49	GX-B1310/21-1-24297	2025. 1. 14	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	
50	GX-B1428/21-1-24297	2025. 1. 14	无缺陷痕迹显示	

51	GX-B1310/21-1-24298	2025. 1. 14	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	
52	GX-B1428/21-1-24298	2025. 1. 14	无缺陷迹痕显示	

53	GX-B1313/21-1-24101~24103	2025. 1. 15	本次共检电力变压器 3台，3台电力变压器所检 项目合格	 <p>2024/12/27</p>
54	GX-B1313/21-1-24104~24109	2025. 1. 15	本次共检电力变压器 6台，6台电力变压器所检 项目合格	 <p>2024/12/28</p>

55	GX-B1328/20-1-25001	2025. 1. 15	本次共检验电器28支，28支所检项目合格	
56	GX-B1328/20-1-25002	2025. 1. 15	本次共检携带式短路接地线11套，11套所检项目合格	

57	GX-B1328/20-1-25003	2025. 1. 15	本次共检绝缘杆4套，4套 所检项目合格	
58	GX-B1328/20-1-25004	2025. 1. 15	本次共检绝缘胶垫 152个，152个绝缘胶垫合 格	

59	GX-B1328/20-1-25005	2025. 1. 15	本次共检验电器2支, 2支 所检项目合格	 <p>2025.1.8</p>
60	GX-B1328/20-1-25006	2025. 1. 15	本次共检便携式短路接地 线1套, 1套所检项目合格	 <p>2025.1.8</p>

61	GX-B1313/21-1-25001~25011	2025. 1. 15	本次共检电力变压器 11台，11台电力变压器所 检项目合格	
62	GX-B1313/21-1-25012~25016	2025. 1. 15	本次共检电力变压器 5台，5台电力变压器所检 项目合格	

63	GX-B1313/21-1-25017~25019	2025. 1. 15	本次共检电力变压器 3台，3台电力变压器所检 项目合格	
64	GX-B1305/21-1-25001	2025. 1. 16	综合判定：合格	