

序号	报告编号	发布日期	结论	影像资料
54	GX-B1312/20-Y-25047~25051	2025. 3. 26	本次共检电力变压器 5台，5台所检项目合格。 。	
55	GX-B1312/20-Y-25052~25055	2025. 3. 26	本次共检电力变压器 4台，4台所检项目合格。 。	
56	GX-B1321/20-Y-25099~25100	2025. 3. 26	本次共检电力电缆2条， 2条电力电缆所检项目合格。 。	

57	GX-B1321/20-Y-25101~25105	2025. 3. 26	本次共检电力电缆5条， 5条电力电缆所检项目合格。	
58	GX-B1321/20-Y-25106~25108	2025. 3. 26	本次共检电力电缆3条， 5条电力电缆所检项目合格。	
59	GX-B1321/20-Y-25109~25113	2025. 3. 26	本次共检电力电缆5条， 3条电力电缆所检项目合格。	

60	GX-B1328/20-Y- 25017	2025. 3. 26	本次共检绝缘手套 24只，24只所检项目合格。 。	
61	GX-B1328/20-Y- 25018	2025. 3. 26	本次共检绝缘鞋18只，18 只所检项目合格。	

62	GX-B1328/20-Y- 25019	2025. 3. 26	本次共检验电器5支，5支所检项目合格。	
63	GX-B1328/20-Y- 25020	2025. 3. 26	本次共检短路接地线4套，4套所检项目合格。 。	

64	GX-B1328/20-Y- 25021	2025. 3. 26	本次共检绝缘杆2支，2支绝缘杆所检项目合格。 。	
65	GX-B1310/21-Y- 25011	2025. 3. 31	符合标准要求。	

66	GX-B1310/21-Y- 25012	2025. 3. 31	符合标准要求。	
67	GX-B1310/21-Y- 25013	2025. 3. 31	符合标准要求。	

68	GX-B1310/21-Y- 25010	2025. 3. 31	符合标准要求。	 A photograph showing a worker wearing a red hard hat and a grey uniform operating a red industrial machine. The worker is positioned on the left side of the machine, which has several red knobs or buttons on top. The background shows an industrial setting with a staircase and other equipment. A yellow timestamp '2025/3/31' is visible in the bottom right corner of the photo.
----	----------------------	-------------	---------	--